









40 D 4S BB




KUH.60028



KUH.60027

KUH.90004




KUH.90003

KUH.10056

KUH.90004



KUH.90003




KUH.90039

WST.0045

WST.0044

x3



8x30mm A 26	6.4 x 50mm B 8	E1 8	E9 2	6.5x48x16 F2 4	L=450mm I5 4
5.0x13mm M 24	O 1	O11 1	4.0x45mm P4 2	3.5x13mm P5 32	3.5x20mm P6 12
3.0x20mm P7 8-10	4.0x35mm R3 4	S23 4	M4x22mm U 8	Z3 4	Z4 4



ISM-KUH-00918





1

$\pm 8 \times 30 \text{ mm}$  A 18	0,05  O11 1
--	---




2





0,05  O11 1
--








3





x3





KUH.70150




4






L=450mm  I5 4	±5.0x13mm  M 24	6.5x48x16  F2 4	 Z3 4	±3.5x20mm  P6 12	±8x30mm  A 8
--	--	--	---	---	---



KUH.10056








KUH.10040




5

6,4 x 50mm  B 4	 O 1	 E1 4
---	---	--




6

6,4 x 50mm



B

4





O

1




E1

4




E1



O


B

7



A=B

BA







8

+3.0x20mm



P7

8-10




9

+3.5x13mm









P5

8









Z4

4



10



L=450mm  I5 4	3.5x13mm  P5 24
--	--








x3

11

M4x22mm  U 8	 S23 4
--	---






x3





12



$\pm 4.0 \times 45 \text{mm}$  P4 2	 E9 2
---	--







13






$\pm 4.0 \times 35 \text{mm}$  R3 4
--








13








80 ZL 2F BB



KUH.40027











8x30mm A 8	6,4 x 50mm B 8	E1 8	E9 2	6.5x48x16 F2 4	35/0mm HG 4
O 1	4.0x45mm P4 2	3.5x13mm P5 8	3.0x20mm P7 4	S23 2	M4x22mm U 4



ISM-KUH-00927

1

6.5x48x16	±8x30mm	±35/0mm	±3.5x13mm
			
F2	A	HG	P5
4	8	4	8



x2


2

6,4 x 50mm



B

4



O

1



E1


4

KUH.90113


KUH.10042

KUH.90114

KUH.40027



E1




3

6,4 x 50mm



B

4



O

1



E1

4

KUH.90113



KUH.10042

KUH.90114






KUH.10041

KUH.40027





E1











4









5
























7

M4x22mm	
	
U	S23
4	2














				 4.0x30mm	 3.0x20mm			 4.0x13mm				 4.0x30mm
A	B	C	D	E	F	I	J	K	M	O	L	N
12	12	1	2	4	15	4	4	8	4	4	2	4




Pakował:	Szanowny kliencie. W razie reklamacji jakościowej lub ilościowej proszę podać nr pakującego oraz nr elementu. Achtung: Bei eventuellen Beanstandungen, bitten wir Sie die Nr. des packers sowie die, des fehlenden bzw. beschädigten Teiles unbedingt anzugeben. Dragi kupci. Prilikom eventualne reklamacije morate obavezno navesti broj pečata koji je na paketu i broj dijelova koji nedostaju ili su oštećeni u paketu. Jedino u tom slučaju možemo prihvatiti Vašu reklamaciju kao valjanu. Unaprijed Vam zahvaljuje Vaš. Dear Customer. We regret to inform you, that in time complaint please give No packer and No missing and spoil element.
----------	--



60 D 1F BB













 A	 B	 E1	 E9	 F2	 HG	 J
8	8	8	2	4	2	4
 O	 P4	 P5	 P7	 R3	 S23	 U
1	2	4	8-10	4	1	2



ISM-KUH-00928

6.5x48x16	±8x30mm	±35/0mm	±3.5x13mm
			
F2	A	HG	P5
4	8	2	4




2

6,4 x 50mm



B

4




O

1




E1

4



E1



B



O

KUH.90011

KUH.90010

KUH.10226

KUH.40007




3

6,4 x 50mm



B

4



O


1



E1

4

E1



B

O





KUH.90011

KUH.90010



KUH.10226

KUH.10225

KUH.40007






4





5

43.0x20mm
P7
8-10





6

$\pm 4.0 \times 45 \text{ mm}$  P4 2	 E9 2
---	---







7














$\pm 5 / 19 \text{ mm}$  J 4
--






8






9





M4x22mm	
	
U	S23
2	1









60 OK-40




KUH.40009










 A	 B	 E1	 HG	 K	 K24
8	8	8	2	2	2
 O	 P5	 P7	 P8	 S23	 U
1	4	8-10	4	1	2







ISM-KUH-00940

 8x30mm A	 35/0mm HG	 3.5x13mm P5	 4.0x30mm P8	 K
8	2	4	4	2






2

6,4 x 50mm		
		
B	O	E1
4	1	4







3



6,4 x 50mm		
		
B	O	E1
4	1	4





4






5










6













7




8









60 D GAZ BB



KUH.40008



KUH.60007

KUH.40008

KUH.10046

KUH.90011


KUH.90010

KUH.90015

KUH.10045


KUH.70151









8x30mm A 8	6,4 x 50mm B 8	E1 8	E9 2	6.5x48x16 F2 4
L28 2	O 0	4.0x45mm P4 2	3.5x13mm P5 8	3.0x20mm P7 8-10



ISM-KUH-00942





1

$\varnothing 8 \times 30 \text{ mm}$  A	$6.5 \times 48 \times 16$  F2	 L28	$\varnothing 3.5 \times 13 \text{ mm}$  P5
8	4	2	8





2

6,4 x 50mm		
		
B	O	E1
2	1	2



3


6,4 x 50mm	
	
B	O
2	1







4

	
E9	P4
2	2




4.0x45mm



KUH.90015




5




6

6,4 x 50mm



B

6








O

1



E1

6



7

3.0x20mm



P7

8-10

