




PL: INSTRUKCJA MONTAŻU

EN: ASSEMBLY MANUAL


CZ: PŘÍRUČKA PRO MONTÁŽ













SK: PRÍRUČKA PRE MONTÁŽ





DE: MONTAGEANLEITUNG

SR: UPUTSTVO ZA INSTALACIJU

NL: MONTAGE-INSTRUCTIES




A x20  $\varnothing 8 \times 35 \text{mm}$	B x16  $\varnothing 3,5 \times 16 \text{mm}$	C x6  $\varnothing 15 \times 20 \text{mm}$	D x8  $\varnothing 21 \text{mm}$	E x20  $\varnothing 15 \times 12 \text{mm}$
F x20  $\varnothing 5 \times 38 \text{mm}$	H x31  26mm	I x4  $\varnothing 6,4 \times 50 \text{mm}$	J x2  $\varnothing 8 \times 1,5 \text{mm}$	K x1  4mm HEX
L x2  350mm	N x4  40mm	O x6  $\varnothing 4 \times 30 \text{mm}$		



No.	L[mm]	W[mm]	H[mm]	PCS	BOX
1	503	430	22	1	1/1
2	470	371	15	1	1/1
3	395	200	15	1	1/1
4	470	400	15	1	1/1
5	428	400	15	1	1/1
6	428	400	15	1	1/1
7	470	70	28	1	1/1
8	469	60	15	1	1/1
9	428	50	22	1	1/1
10	428	50	22	1	1/1
11	350	120	15	1	1/1
12	336	120	15	1	1/1
13	360	355	2,5	1	1/1
14	498	385	2,5	1	1/1
15	350	120	15	1	1/1


1

A x 6












Ø8x35mm




F x 8







Ø5x38mm








2




3




4



5




$$L = L1 + L2$$




6

L1x2





350mm




Ox4






Ø4x30mm






7






8






9




10






11






12



13




14





15

Fx4




Ø5x38mm





16

E x4




Ø15x12mm





17



Hx18



26mm




$A=B \equiv 90^\circ$




18

Cx6






Ø15x20mm

Ox2




Ø4x30mm





19

Fx2




Ø5x38mm





20




Ax2






Ø8x35mm



21




22





23



Hx13



26mm




$A=B \equiv 90^\circ$




24

Bx4




Ø3,5x16mm

Dx2





Ø21mm

L2 x2



350mm






25

J x 2




Ø8x1,5mm






26

B x 2



Ø3,5x16mm



27

D x 6



Ø21mm

